

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3547

Date Inspected Aug 16

I so how and location from
first manhole down stream

House No. 311

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? yes

Name of Contractor

Geo Early

Was attached to main

Show by diagram relation of lateral to wall of building served.



52 ft pipe

7 1/2

Main Sewer North →

21st St N.W.

Signed

A. T. Boyd

Inspector for City

Filed at Engineer's Office

AUG 19 1911

Remarks:

Lateral connected to lateral at curb 11 ft from street
line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3547

PERMIT TO TAP SEWER

Massillon, O. Aug 14th 1919

Received of Mr. M. L. Linn fee of \$ 2.00

for which permission is granted Her E. Linn

to tap Sanitary sewer, on the Massillon

of 21st St. Ave., Type of Street St.

the premises being Lot No. 7214 — 7232, House No. 311

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor Her E. Linn

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.