FOLLOWING DATA TO BE ANSWERED BY INSPECTOR and signed when returned $N_{\rm c}^{\rm o}=3555$

Date Inspected Ask 16	I so how and location from first manhole down stream.			
House No. 24	Distance from first manhole			
Size of pipe used 6 111	down stream to ditch at curb line and depth			
Was lateral at curb? 1968	Name of Contractor Sur Early			

Was attached to main				
Was attached to main				
Show by diagram relation of lateral				
Show by diagram relation of lateral				

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3555 PERMIT TO TAP SEWER

d lecstjon from dawn stroam	den serie es i	Iassillon, O., 👤	·文73 19
Received of			fee of \$
for which permission is granted	QU.,(yest	
to tap	nollinging (/ sewer, c	n the	EST FEBRUSE BEW
of 100 DF	Av	e., Type of Stree	reduct
the premises being Lot No.		t., , House No.	마다를 가게 되는 때 하는 하는 것 같아 모든 사람들이
Work to be done in accordance with (Ordinance No. 2:	323, duly passed l	by the City Council, and R
the Department of Public Service.			
Name of Contractor Con	2		

NOTE. This permit covers work outside of building only. Any work inside walls of by

is subject to Massillon Board of Health Regulations.