

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

10-13

No. 3561

Date Inspected Oct-

I so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? No

Name of Contractor

Was attached to main at-Y

Show by diagram relation of lateral to wall of building served.

Geo Early
House



Signed

A. F. B. [Signature]

Inspector for City

Filed at Engineer's Office

OCT 6

Remarks:

lateral connected to main at Y 26 ft from main Hal

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3561

PERMIT TO TAP SEWER

Massillon, O., Oct. 1st, 1920

Received of J. E. Early fee of \$2.00

for which permission is granted Her Early

to tap sanitary sewer, on the North

of Lee May E Ave., Type of Street
St.,

the premises being Lot No. O.L 339, House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor Her Early

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.