

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3569

Date Inspected Oct-25

I so how and location from
first manhole down stream

House No. 2557

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

Jed Brunner



Main Sewer west 1/6

Signed A. F. Boyd

Inspector for City

Filed at Engineer's Office

OCT 31 1917

Remarks:

Lateral connected to lateral at main 17.8 ft from man
Hole

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3569

PERMIT TO TAP SEWER

Massillon, O., Oct. 23 19

Received of

Home H. L. L. L.

fee of \$ 2.00

for which permission is granted

Jesse Brumby

to tap

sanitary

sewer, on the

south

of

Lincoln Ave.,

Type of Street
St.,

paved

the premises being Lot No.

3669

House No.

2551

Work to be done in accordance with Ordinance No. 2923, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

Jesse Brumby

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.