FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Nov 4	I so how and location from first manhole down stream
House No. 60 9 Size of pipe used 6 m	Distance from first manhole down stream to ditch at
Was lateral at curb?	name of Contractor 4 House Survey
Show by diagram relation of lateral	to wall of building served. House 5 1/2 66 Higher and and the served are to be served as the served are to be served.
i bus diagrafi dita Congol, and i	one pramisespelag Normal Section of Market West Section of World Section o
	Main Sever South
Signed A T B 1 Inspector	26 th St. E NOV 7
Remarks: Saltral Com	nected to lateral curb 8% ft from Atra

Nº 3574

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	an how and lucation from	Massillon, O.,	Now 2	19
Received of	elogus Andluva sin Alluva ninga ban egali	<u> </u>	fee o	f \$.2
for which permission	is granted // //	<u>Land</u>	en-A-ini =+	
of 26		wer, on the		;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;
the premises being Lo	ot No. 6920	St.,) House		04
Work to be done in a	ccordance with Ordinance	No. 2323, duly passe	ed by the City Cou	ncil, and Ru
the Department of P	FUH.	\mathcal{A}		
Name of Contractor	4			

is subject to Massillon Board of Health Regulations.

This permit covers work outside of building only. Any work inside walls of bi