The matrices of the following data to be answered by inspector and signed when returned $N^o_{\rm c}=3582$

Date Inspected	I so how and location from first manhole down stream
House No. 32	Distance from first manhole down stream to ditch at
Size of pipe used 6 nn	curb line and depth
Was lateral at curb? NO Was attached to main Short	Name of Contractor Ald Brunker
Show by diagram relation of lateral to	wall of building served. House
inga Norsett Viji Sparing Sparing Stranger	39 H-frifice 19 alls
	Sa Main Dewer West
Signed A F. Boryol	Buton and Wife 11/25/Filed at Engineer's Office
Inspector for Remarks: Saleral Councer	cted to lateral at curb 5 ft from Ma

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3582

PERMIT TO TAP SEWER

######################################	v stel location da nvol alada	od do d Joseph M	assillon, O.,	hin-	73
Received of #	M. E		tz	A Carlotte	ee of \$_2
for which permission is gra	inted		(Born	Le:	
to tap Messes L					~#
of Buton	22.3.	Ave St	Type of S	treet	41_
the premises being Lot No.	922	0	, House	No <u>공</u>	2
Work to be done in accord	ance with Ordin	ance No. 232	23, duly passe	ed by the City	Council, and R
the Department of Public	Service.	24	<u>Garage</u>		
	nit covers work	outside of b	uilding only.	Any work in	iside walls of b

is subject to Massillon Board of Health Regulations.