FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED - Nº -3586

Date Inspected Dac 2 not	I so how and location from first manhole down stream
House No.	Distance from first manhole
Size of pipe used 10 in	down stream to ditch at curb line and depth
Was lateral at curb? Moran Sewe	
· Was attached to main	Name of Contractor Des Brunker
Show by diagram relation of lateral to	
	Work to be done the Mondane with Critinate Na. 23
	Storm Semere in Prastal
Signed A, A. Boyd	Postal OT DEC 18
Inspector for	· City
Remarks: Mun Dewe	cruming East from hetch bason in Posta

GROFFURIUS SERVICE

Not Platied OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 3586 PERMIT TO TAP SEWER Massillon, O.,____ for which permission is granted. Ave., Type of Street Ang the premises being Lot No. ___/2/ House No. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rt the Department of Public Service. Name of Contractor. This permit covers work outside of building only. Any work inside walls of bi is subject to Massillon Board of Health Regulations.