FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N_{\cdot}^{\circ} = 3624$ Date Inspected I so how and location from first manhole down stream. House No. 760 Distance from first manhole down stream to ditch at Size of pipe used 4 curb line and depth... Was lateral at curb? 122 Name of Contractor. Was attached to main____ Show by diagram relation of lateral to wall of building served. ye., (Type of Street o 2222, daily pared by the City County, and Index of

Hol

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

3624 Massillon, Received of. for which permission is granted Ave., Type of Street the premises being Lot No. 3943

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ruthe Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building only. Any work inside walls of building to Massillon Board of Health Regulations.