## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Aug I so how and location from first manhole down stream. House No. 872 Distance from first manhole down stream to ditch at Size of pipe used & and curb line and depth. Was lateral at curb? Was attached to main\_\_ Show by diagram relation of lateral to wall of building served. Residing Street ance No. 2823, doly passed by the City Council and Males 4

3631

office of the director of public service  $N^{0}$  3631  ${
m PERMIT TO TAP SEWER}$ 

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru

the Department of Public Service.

NOTE. This permit covers work outside of building only. Any work inside walls of building only. Any work inside walls of building only.