

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N^o 3635

Plotted

Date Inspected *Sep 30 th*

I so how and location from
first manhole down stream

House No. *1827*

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used *6 in*

Was lateral at curb? *yes*

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

House

6
40 ft pipe
7

Main Sewer East

Main Ave West

OCT 15 1937

Signed *A. F. Boyd*

Inspector for City

Filed at Engineer's Office

Remarks:

lateral connected to lateral at curb 7 ft from strait line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3635

PERMIT TO TAP SEWER

Massillon, O., Oct 1st 19

Received of R. J. Zule fee of \$ 2.00

for which permission is granted J. Brumber

to tap sanitary sewer, on the south

of Main Ave., Type of Street dist.

the premises being Lot No. 10330, House No. 1827 1831

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rt the Department of Public Service.

Name of Contractor J. Brumber

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.