

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 3646

plotted

Date Inspected *April 21*

I so how and location from
first manhole down stream

House No. *2029*

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used *6 in*

Was lateral at curb? *yes*

Name of Contractor

Geo E early

Was attached to main

Show by diagram relation of lateral to wall of building served.



*Tremont ave S.W.
main sewer East ←*

Signed *A. G. Boyd*

Inspector for City

Filed at Engineer's Office

APR 30 1933

Remarks:

*lateral connected to lateral at curb even with
strait line on House*

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3646

PERMIT TO TAP SEWER

Massillon, O.,

Apr 19th 19

Received of

Ralph Reitmeyer

fee of \$ 2⁰⁰

for which permission is granted

Her Early

to tap

Sanitary

sewer, on the

South

of

Tremont Ave. St.

Ave., Type of Street

paved

the premises being Lot No.

10 337

, House No.

2029

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

Her Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.