FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected OA & 1 House No. 2 / 5	I so how and location from first manhole down stream Distance from first manhole
Size of pipe-used, & A	down stream to ditch at curb line and depth
Was lateral at curb? <i>人人</i> とか	Name of Contractor Des Brunker
Was attached to main	
show by diagram relation of latera	
Show by diagram relation of latera	
Show by diagram relation of latera	of 5 we missing 33 ft hipe
Show by diagram relation of latera	25 2 A Work to Decordance with Cardinera. No. 2538
Show by diagram relation of latera	of the said of the Section of the Se

3656

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3656

PERMIT TO TAP SEWER

	more accessed bus wedge. I
	Received of Missing Annual fee of \$200
ď	for which permission is granted to tap the sever, on the sever of the sever.
	of Lordh ave As Ave., Type of Street 1700
	St., the premises being Lot No. 1633 1432, House No.
	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.
	Name of Contractor eso Brunker Poge 16
	NOTE. This permit covers work outside of building only. Any work inside walls of bu

is subject to Massillon Board of Health Regulations.