

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

*Indexed
Suber*

4-14

No 3689


Date Inspected 5-25-34 I so how and location from
House No. 820 or 856 Two first manhole down stream
Size of pipe used 6" Distance from first manhole
down stream to ditch at
curb line and depth

Was lateral at curb? Yes

Was attached to main Yes Name of Contractor

Show by diagram relation of lateral to wall of building served.

Geo Early



*Geo. Early place 1st sec of
Soil pipe into Bldg. Set
it so as to have a fall out.*

*Good Fall in Line straight from
Wall to lateral.*

Del Early laid the pipe.

*Rotted out
when lateral
uncovered -
OK.*

Signed Charles Wallace
Inspector for City

Filed at Engineer's Office

Remarks: Detail already straight line - everything went along
OK,

MAY 25

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3689

PERMIT TO TAP SEWER

Massillon, O., May 22 1922Received of H. E. Early fee of \$ 2.00for which permission is granted H. E. Earlyto tap Sanitary sewer, on the Eastof Channing St. N. 1/2 Ave., Type of Street Dist
St.,the premises being Lot No. 2863, House No. 856 820

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor H. E. Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.