

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

№ 3690

Date Inspected May 29 - 1934

House No. Filling Station SW Cor
Tremont & 17th St SW.

Size of pipe used.....6"

Was lateral at curb? *Yes Sew. Rec. ok*


Was attached to main Yes

Show by diagram relation of lateral to wall of building served.

I so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth_____

Name of Contractor



Signed

G. C. Wallace

Inspector for City

Filed at Engineer's Office

MAY 20 19

Remarks

Remarks: Rock dig ditch Geo. Early (Delbar) laid the pipe, pipe had a
fall over over 13/8" per ft.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3690

PERMIT TO TAP SEWER

Massillon, O.,

May 22 19

Received of

fee of \$ 2.

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street
St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.