

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3691

Date Inspected June 6th 1934

House No. 64- 10th St SE

Size of pipe used 6" & 4"

Was lateral at curb? Yes

Was attached to main Yes


I so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor Geo Early

Show by diagram relation of lateral to wall of building served.

6" Pipe (old & new) from
Curb to Wye - 4" (old &
new) from Wye



Signed Geo Wallace

Inspector for City

WELLMAN AVE SE.

Filed at Engineer's Office

1861 9 N

Remarks: Relay Job - used Prestite joints - had cable out in lateral under street
& cleaned out pipe - trouble before with roots

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 3691

PERMIT TO TAP SEWER

Received of L. E. Halcutt Massillon, O., June 6 1919
 fee of \$ 2.00

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street
 St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.