

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3692

Date Inspected June 8 1934

I so how and location from
first manhole down stream

House No. 937

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"

Was lateral at curb? No Curb - Lateral OK.

Name of Contractor


Was attached to main yes

Show by diagram relation of lateral to wall of building served.

Geo. Early

*flushed main for
1 1/2 hours:
Note - no city water
in house*

*75 Deep
Top End to
Top pipe*



*Took out 6 pails of gravel from 1st MH Downstream
" " 4 " " " 2nd MH
Don't know how much was flushed down the sewer*

Signed Geo. C. Vallero

Inspector for City

Filed at Engineer's Office

JUN 8 1934

Remarks

*Stream on lateral broken - pipe was full of gravel investigated
found 1st MH down stream pipe full of gravel - 2nd manhole downstream stopped with sewer*

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3692

PERMIT TO TAP SEWER

Massillon, O., June 8 19Received of Geo. E. Early fee of \$ 2.50for which permission is granted Geo. E. Earlyto tap Main Street sewer, on the Eastof Chancellor Ave., Type of Street dist.
St.,the premises being Lot No. 4235 4171, House No. 937

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by
the Department of Public Service.

Name of Contractor Geo. E. Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.