

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3694

Date Inspected June 15th 1934

House No. 2541

Size of pipe used 6" up to House

Was lateral at curb? Yes

Was attached to main Yes ran rods



Show by diagram relation of lateral to wall of building served.

I so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor

Geo. Earley
into main



Signed Geo C Wallace
Inspector for City

Filed at Engineer's Office

Remarks:

Prestite joints used - good job all around.

JUN 15 1934

Mr. Pricker saw Geo. Early and asked him to lay this sewer.

1:00 PM
June 15 - 1934

No. 3694

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Massillon, O., June 15 1934

Received of Geo. Early fee of \$ 2.00

for which permission is granted

to tap Main St. sewer, on the

of R. C. B. Ave., Type of Street dead
St.,

the premises being Lot No. 41522, House No. 2571

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor Geo. Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.