

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3716

Date Inspected 4-17-35

I so how and location from
first manhole down stream was attached to main with 6

House No. 931

Distance from first manhole
down stream to ditch at
curb line and depth 5 ft. Deep, 112' FROM MANHOLE


Size of pipe used 6"

Was lateral at curb? NO

Name of Contractor GEO. EARLY

Was attached to main YES

Show by diagram relation of lateral to wall of building served.



Signed Shurter
Inspector for City

Filed at Engineer's Office APR 30 1935

Remarks CARPENTER CONTRACTOR said joint made in 4" soil pipe was better than Plumber would have made.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3716

PERMIT TO TAP SEWER

Massillon, O., April 15 1918

Received of Geo. E. Early fee of \$ 2.00

for which permission is granted Geo. E. Early

to tap Sanitary sewer, on the West

of 10th St. Ave., Type of Street dead
St.,

the premises being Lot No. 917, House No. 951

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1 of the Department of Public Service.

Name of Contractor Geo. E. Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

8/17