FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED -3734 Date Inspected 6-25-35 I so how and location from first manhole down stream House No. 427 Distance from first manhole down stream to ditch at 7.19 livieses or LIX & OFALLEY down stream to ditch at Size of pipe used... for which permission is aren Was lateral at curb? YES. Name of Contractor G=0 = 0 (Y) Was attached to main..... Show by diagram relation of lateral to wall of building served. CEMENT TOWTS USED WITH JUTE RAN RODS THRU Lateral before connection was made line was Clear PLENTY OF GALLING SOCURB. WATER AVE NW. NO.CUEB. JUN 2 6 1935 Astronometric Amazi Filed at Engineer's Office. Inspector for City Remarks: WYS PLACED 13'5" FROM CURB LakatCURB I'East of East side Hous

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

mora nalizaci bas vica ce Somment Jeril /Massillon./O.,... for which permission is granted Ave., Type of Street the premises being Lot No Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

AIT TO TAP SEW

NOTE. This permit covers work outside of building only. Any work inside walls of building only. Any work inside walls of building only.

Name of Contractor.