


**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3736

PHRS FOR INSP.

Date Inspected 7-12-35 I so how and location from
first manhole down stream WYE Pole was Found at exact measur
House No. 1650 Distance from first manhole
Size of pipe used 6" WITH TITE down stream to ditch at
curb line and depth 128' FROM M.H. SOUTH 7' DEEP
Was lateral at curb? YES # 10 Name of Contractor L. Smart
Was attached to main WYE Pole Found
Show by diagram relation of lateral to wall of building served.

Plenty Fall in this line.



Signed Shertzer

Inspector for City

Filed at Engineer's Office

JUL 12 1935

JUL 12 1935

Remarks: Lateral at curb is 23' south of south side of House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3736

PERMIT TO TAP SEWER

Massillon, O.,

7-2

19

Received of

S. S. Smith

fee of \$2.00

for which permission is granted

Mr. Caldwell

to tap

S. S. Smith

sewer, on the

E

of

10th NE

Ave., Type of Street

St.,

drift

the premises being Lot No.

84.58

House No.

1650

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

S. S. Smith

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

6/49