

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3737

Date Inspected 7-22-35

House No. 16

Size of pipe used 6" WITH PRESS TILE

Was lateral at curb? YES # 4

Was attached to main _____

Show by diagram relation of lateral to wall of building served.


THE CELLAR DRAIN IS 5'-6" SOUTH OF
THE NORTH SIDE OF HOUSE AND 158' BELOW
HOUSE FND.

3 hrs. for Insp.
FOUND + ON CURB.

I so how and location from and in REAR connection on present 4
first manhole down stream Line 15.84" East of West Line curb

Distance from first manhole
down stream to ditch at
curb line and depth 10' East of M.H. 2 and 6.5 DEEP

Name of Contractor Smart



Signed Shertan
Inspector for City

Filed at Engineer's Office

JUL 22 1935

Remarks: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3737

PERMIT TO TAP SEWER

Massillon, O.,

July 11, 19

Received of

Harry Rens

fee of \$ 2.00

for which permission is granted

to tap Sanitary sewer, on the

of Burton Ave N.W. Ave., Type of Street disc
St.,

the premises being Lot No. 7833, House No. 16

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

L. W. Rens

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.