FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED I so how and location from

 $M_{\mathbf{0}}$ 3767 Date Inspected. first manhole down stream. House No. .. Distance from first manhole down stream to ditch at Size of pipe used_ curb line and depth..... Was lateral at curb? Name of Contracto Was attached to major Show by diagram relation of lateral to wall of building served.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3767

PERMIT TO TAP SEWER

	moji sekepa ins mesis masi sidi	Mar	ssillon, O.,	- 1921 oni
Received of	stadaša isni giva i indaigrafias ėmia bes	errei di Bilani e key ler bublikan		fee of \$
for which permission	is granted		T=1.4	4
to tap		sewer, on	the	e Linguis de cois
of 12.7	herrentenil) 	Type of Street	inversily vilverife. A.A.
the premises being Lo	t No	St.,	, House No	664
Work to be done in a	ccordance with Ordi	nance No. 2323	duly passed by t	he City Council, and R
the Department of P	ublic Service.			
Name of Contractor	12 r &	=44-		

NOTE. This permit covers work outside of building only. Any work inside walls of buils subject to Massillon Board of Health Regulations.