

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Date Inspected 8/26/00 I so how and location from
first manhole down stream.
House No. 1418 Distance from first manhole
down stream to ditch at
Size of pipe used 6" curb line and depth
Was lateral at curb? Yes
Was attached to main Yes Name of Contractor 2555
Show by diagram relation of lateral to wall of building served. 2

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

Walnut Rd, S.W.

Signed

Inspector for City

Filed at Engineer's Office

Remarks:

8/26/06

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3826

PERMIT TO TAP SEWER

Massillon, O.,

726

19

Received of

L. W. Luman

fee of \$2.00

for which permission is granted

Frank Samuels & Son Co

to tap

Sanitary

sewer, on the

East

of

Walnut St.

Ave., Type of Street
St.,

dirt

the premises being Lot No.

3026

House No.

418-12 1/2

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, duly passed by the Board of Public Service.

Name of Contractor

L. W. Luman

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

7-1-15-37