

North

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

No. 3828

Date Inspected 9/7/36

I so how and location from
first manhole down stream

House No. 2518

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 6"

Was lateral at curb?

Was attached to main

Name of Contractor

Show by diagram relation of lateral to wall of building served.



Lincoln Highway N.W.

Signed

Frank B. Jones

Inspector for City

Filed at Engineer's Office

9/7/36

Remarks:

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.