

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3862

Date Inspected 4-1-37

House No. 233

Size of pipe used 4"

Was lateral at curb? YES 4' Lat.

Was attached to main

I so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth


256' From M.H. at alley: 6' Deep at curb

Name of Contractor

Geo Earley

Show by diagram relation of lateral to wall of building served.

allowed 3/4" fall per pipe on account of getting
to rear of basement: service side joints used



S. Curb.

Main Sewer

Signed Doc.

Inspector for City

Filed at Engineer's Office

APR 4 1937

Remarks:

Lateral curb is 8' west of west side of house and is 6' deep

OK
LAW

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No 3862

Massillon, O.,

Received of

fee of \$ 2.00

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street

St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.