

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No 3870

Date Inspected 4-20-37

House No. 1306

Size of pipe used 6"

Was lateral at curb? Yes

Was attached to main service side

Show by diagram relation of lateral to wall of building served.

I so how and location from

first manhole down stream 32'±16" vs. 17' laid with plenty for


Distance from first manhole

down stream to ditch at


curb line and depth 233'± From MH North 41'± from MH. 50'

Name of Contractor

Geo Early



*original measurement on
found wire pole on dot.*



Signed Doc

Inspector for City

Filed at Engineer's Office

APR 21 1937

Remarks Measurements from MHoles taken in E. of street at right angles to cor-
rior at curb.

4
53
1.50

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3870

PERMIT TO TAP SEWER

Massillon, O.,

Received of

fee of \$

for which permission is granted.

to tap

sewer, on the

of

Ave., Type of Street

St.,

the premises being Lot No.

, House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.