

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3871

Date Inspected 4-20-37

I so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at

Size of pipe used 6"

curb line and depth

74° - 7° Deep - 5' W. of Curb


Was lateral at curb? Yes

Name of Contractor

L. H. Smart

Was attached to main

Show by diagram relation of lateral to wall of building served.



H. P. [Signature]
Signed

Inspector for City

Filed at Engineer's Office

Remarks: EX'S SEWER LATERAL WAS 6" W. OF CURB

4
17

RECEIVED DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WITH RETURNED

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3871

PERMIT TO TAP SEWER

Massillon, O.,

4/19 19

Received of

fee of \$

2.00

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street
St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, duly passed by the Board of Health, and approved by the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.