


**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3901

Date Inspected 7/14/37 I so how and location from
first manhole down stream 217 - 2' deep
House No. 885 Distance from first manhole
down stream to ditch at
Size of pipe used 6" curb line and depth 222 -
Was lateral at curb? N.O. Name of Contractor Geo. Easley
Was attached to main N.O. HOUSE.
Show by diagram relation of lateral to wall of building served.



Signed John Easley Filed at Engineer's Office JUL 15 37
Inspector for City

Remarks: Y on main encased in concrete

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3901

PERMIT TO TAP SEWER

This soil pipe was put in after
inspector left job

Massillon, O.,

7/13

Received of

Geo. Early

fee of \$

2.00

for which permission is granted

Geo. Early

to tap

Sanitary

sewer, on the

west

of

10th St. N. E.

Ave., Type of Street

driv

St.,

the premises being Lot No.

5273

House No.

885

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

Geo. Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

John Ehmer reports that on 12-20-37 he was called to this place and found wash water in cellar. Investigation showed a bad joint where soil pipe and riser connected. The residents of that time said that Geo. Early made this connection. Our inspector has nothing to do with sewer in side of cellar wall, and sewer contractor has no right to lay soil pipe.