## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 3903

Date Inspected 7/22/37	I so how and location from 192	
/House No. /620	Distance from first manhole	
Size of pipe used 6:	curb line and depth 192 6 Mark	
Was lateral at curb?	Name of Contractor Grown Landy	
Was attached to main Xez	Name of Contractor 25 25 25 25 25 25 25 25 25 25 25 25 25	
Show by diagram relation of lateral to $H_{\mathcal{Q}}$	to wall of building served.	
10:6"—3X		( ok elde
aga , (tongo) with eft the Council, aga	Le 6 descurs.	N:
1 / 2/151	Find at Engineer's Office	JUL 23 3
Signed John January Inspector in the whole the state that the stat	Filed at Engineer's Office for City	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 $N_c$  3903

## PERMIT TO TAP SEWER

Massillon, O. July 27 Ave., Type of Street. the premises being Lot No. 0 4 3 6 7 , House No. 16 Z O Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

Name of seam of seam of Name of seam of seam of Name of Seam o

NOTE. This permit covers work outside of building only. Any work inside walls of bi is subject to Massillon Board of Health Regulations.