FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected 8/20/37 I so how and location from 155 first manhole down stream House No. 22/ Distance from first manhole down stream to ditch at Size of pipe used 6 curb line and depth. Was lateral at curb? Was attached to main Show by diagram relation of lateral to wall of building served. LLENAVE, N.W. AUG 27 3Z Filed at Engineer's Office. Inspector for City

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Massillon. O for which permission is granted. Ave., Type of Street the premises being Lot No. 77 (2 (2 Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ri the Department of Public Service.

NOTE. This permit covers work outside of building only. Any work inside walls of building only. Any work inside walls of building only.

Name of Contractor