## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 3914

Date Inspected 7//0/37	I so how and location from first manhole down stream	202'	
House No. 34/-374/75 E. Size of pipe used 6	그는 그는 경우 중에 다른 사람이 되는 것이 되는 것이 없는 것이 없는 것이 없다면 되었다면 하게 되었다.	102 710	<i>"</i>
Was lateral at curb? Yes	Name of Contractor Lorente	misolishin sp Lar Ley	
Was attached to main /		es (es estation)	
Show by diagram relation of lateral to wa			-7 deef.
SOUTH. AVE. S.L	5, 34 (0.131)	edesiment and	The second secon
Shee Toddood valle of the lineage stabilities.	arkonggana) him emetrogrami o 202 Corb Line	nob ed or drov	"desen
144.0			/
Signed Och Elm	Filed at Eng		SEPIO 37 C
Inspector for C	ity		

## FFICE OF THE DIRECTOR OF PUBLIC SERVICE

## IT TO TAP SEWER for which permission is granted Ave., Type of Street. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service. Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of bis is subject to Massillon Board of Health Regulations.