FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N_{\cdot}^{\circ} = 3916$

Date Inspected 9-21-37 so how and location from No. of M. @ Lindbergh + 18" first manhole down stream. House No. 3/2 Distance from first manhole Size of pipe used 6"1.5.P down stream to ditch at curb line and depth // 3 - 4 Deep 124 for MH of Wycli Was lateral at curb? LA, Smar Name of Contractor___ Exis /oferal= Was attached to main_ Show by diagram relation of lateral to wall of building served: Serviceside your 45 801, Filed at Engineer's Office... Inspector for City Remarks:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

3916

PERMIT TO TAP SEWER

Massillon, O. for which permission is granted Ave., Type of Street the premises being Lot No. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service. NOTE. This permit covers work outside of building only. Any work inside walls of be

is subject to Massillon Board of Health Regulations.