

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3921

DATE INSPECTED 10/4/37

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

280

HOUSE NO. 3261

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

280 — 9' deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



CURB LINE.

LINCOLN WAY N.W.

SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OCT 5 '37

REMARKS:

No. 3921

PERMIT TO TAP SEWER

2/2

116

DATE OF PERMIT 10-4

MASSILLON, OHIO, 19:

RECEIVED OF

L. W. Smart

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

D. Jones

TO TAP

Sanitary

SEWER, ON THE

South

OF

Lincoln W. M. W.

AVE., TYPE OF STREET

Brick

THE PREMISES BEING LOT No.

10220

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

L. W. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.