

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 3922

DATE INSPECTED 10/9/37

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

10'

HOUSE NO. NEW HOUSE

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

10'

9'6" deep


WAS LATERAL AT CURB? YES.

NAME OF CONTRACTOR

Geo Earley

WAS ATTACHED TO MAIN YES.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OCT 11 1937

REMARKS:

LENOX AVE N.E.

○ M.H.

NO. 3922

PERMIT TO TAP SEWER

MASSILLON, OHIO,

10-9-1937

RECEIVED OF

M. P. Kinch

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Geo. Early

TO TAP

Sanitary

SEWER, ON THE

North

OF

Lebanon

AVE., TYPE OF STREET
ST.

Brick

THE PREMISES BEING LOT No.

8801

HOUSE No.

(new)

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo. Early

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.