

Nº 3924

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10/16/37

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

5.

HOUSE NO. 306

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

5' 6.3" deep

WAS LATERAL AT CURB? REPAID.


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Geo. Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

This line from Main to Basement
Rebuilt to get cellar drain



← N 23TH ST. N.W.

6.3" deep at Main.

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

NOV 1 37

REMARKS:

Ehmer Stopped work 3' from wall - this point in
is up to plumber - (See) Complaint in on this Nov 1 1937

NOT TO BE ANSWERED BY INSPECTOR OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3924

PERMIT TO TAP SEWER

MASSILLON, OHIO,

19:

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.