


**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

**Nº 3928**

DATE INSPECTED 10/25/37 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 82'  
HOUSE NO. 2023 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 82' 5'6" deep  
SIZE OF PIPE USED 6 WAS LATERAL AT CURB? Yes NAME OF CONTRACTOR Geo Carley  
WAS ATTACHED TO MAIN Yes SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John Phemer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Old line was full of roots and had to be taken out and relaid with 6" pipe don't no how they are in cellar.

N<sup>o</sup> 3928

# PERMIT TO TAP SEWER

MASSILLON, OHIO, \_\_\_\_\_ 19

RECEIVED OF

*Paul Vogt*

FEE OF \$ 3.00

FOR WHICH PERMISSION IS GRANTED

*Geo. Early*

TO TAP

*Sanitary*

SEWER, ON THE

*North*

OF

*Franklin D. East*

AVE., TYPE OF STREET

*Brick*

THE PREMISES BEING LOT No.

*6113*

House No.

*2023*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Geo. Early*

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.