

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 3931

DATE INSPECTED _____ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 47


HOUSE NO. 124 DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6 DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 47 6'6" deep

WAS LATERAL AT CURB? Yes NAME OF CONTRACTOR _____

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____ FILED AT ENGINEER'S OFFICE _____

REMARKS: This M.H. is up stream from House

No. 3931

PERMIT TO TAP SEWER

Mary Ewicka

MASSILLON, OHIO, *Feb 30* 19*14*

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
St.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

6/52

20

114

inf.

Joe Cheramy

M. Ewicka Joe Cheramy

Sanitary

North

Harmon

Dirk

3587

124

Joe Cheramy