

Nº 3934

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

10/27

DATE INSPECTED 11/20/37

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

35'

HOUSE NO. BEAUTY HILL

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

35'

7'

SIZE OF PIPE USED

4


WAS LATERAL AT CURB?

NAME OF CONTRACTOR

Joe Chercony

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



WALNUT RD. S.W.



SIGNED

John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

started at Y. on main

ok
slower

