

4

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 3941

DATE INSPECTED 12/7/37

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

45 up stream

HOUSE NO. 1015

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

45 — 7'd.

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Geo Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

HOUSE

10' from house

8' deep

4' deep

CURB LINE.

start at 25' curb.

M.H. O

45'

SIGNED

John Ehlers
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

DEC 8 '37

REMARKS:

relaid part of old sewer 25' of curb line

$$\frac{6}{18}$$

NO 3941

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

BOTH IDENTICAL DNA FROM GR 71
 MATCHED SUSPECT BUDHARSA TRIPLE

MASSILLON, OHIO

19

RECEIVED OF

_FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAF

SEWER. ON THE

OF

AVE., TYPE OF STREET
ST.

THE PREMISES BEING LOT NO.

HOUSE No

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.