


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 3946

DATE INSPECTED 12/23/37 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 179'
HOUSE NO. 2623 DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
SIZE OF PIPE USED 6" CURB LINE AND DEPTH 179' 6'6" deep.
WAS LATERAL AT CURB? Yes NAME OF CONTRACTOR Smart
WAS ATTACHED TO MAIN Yes
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-23-37

REMARKS:

DEC 23 '37

9/48

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 3946
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/23 19:26
RECEIVED OF L. W. Lambert FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Thomas Brown

TO TAP Sanitary SEWER ON THE South

OF Rh. de Colaba AVE., TYPE OF STREET dist
ST.,

THE PREMISES BEING LOT No. 4515, HOUSE No. 2623

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. W. Lambert

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.