

No. 3947

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/7/38

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

117'

HOUSE NO. 821

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

117' 6' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR


Geo. Earley

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

CAMPBELL CIRCLE.

old line  
all full of roots  
tree looked like small  
weeping willow  
cement joints on old line  
new fine GK joints



SIGNED

John Thomas  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: THIS IS A RELAY. JOB. OLD PIPE TAKEN OUT REPLACED BY NEW.

No. 3947

# PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/7 19

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE., TYPE OF STREET  
St.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.