

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 3964

DATE INSPECTED 5/5/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE No. 518

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4"


WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LINCOLN WAY, W.



SIGNED

John Thomas
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

MAY 6

REMARKS:

Start 9' in from end of brick pavement on a lateral and 9' off from lot line concrete walk in alley.

NO 3964

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

~~No Record~~

MASSILLON, OHIO, 5/5 19

RECEIVED OF

Mr. Fellabone

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

Mr. Fellabone

TO TAP

Sanitary

SEWER, ON THE

North

OF

alley end of 6th St.

AVE., TYPE OF STREET

Street

THE PREMISES BEING LOT No.

433

House No.

518 Lin Hwy

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo. Parry

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.