

✓
3
23

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 3971

DATE INSPECTED

6/3/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

269'

HOUSE NO.

840

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

269'

6'd

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

Yes

WAS ATTACHED TO MAIN

Yes

NAME OF CONTRACTOR

Geo Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SHEFFIELD AVE. N E.

HOUSE

8' d.

8' d.

6' d.

CURB LINE

269

SIGNED

John E. Egan

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK 4/4/38 H.M.F.

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 3971
PERMIT TO TAP SEWER

1:00

DATE ISSUED 6/3 1915
MASSILLON, OHIO.

RECEIVED OF Henry Early FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED 1 Line to Bain

TO TAP Sanitary SEWER ON THE North

OF Shaffield Ave. N.E. AVE., TYPE OF STREET dirt
ST.,

THE PREMISES BEING LOT No. 3951, House No. 840

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Henry Early

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.