

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

*Index 100
Page 27*

DATE INSPECTED 7/23/38 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 150'

HOUSE NO. 45 - 47 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 150' - 9' 7" deep at M

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? NO NAME OF CONTRACTOR See Earley

WAS ATTACHED TO MAIN NO


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ERIE ST. N.

N. →

Line relaid old line fall was in wrong direction always giving trouble.

Asphalt Pavement



SIGNED John Elmer INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE July 26 '38

REMARKS: RENEWED LINE FROM MAIN.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3979

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/20 19

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.