

9
11

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3982

DATE INSPECTED 8/8/58

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

48'

HOUSE NO. 2873

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

48'

4' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes


NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LINCOLN WAY, N.W.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

AUG 9 '58

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3982

PERMIT TO TAP SEWER

MASSILLON, OHIO, Aug 1 1919

RECEIVED OF

L. H. Smart

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

W. A. Lutton

TO TAP

SEWER, ON THE

OF

Lincoln May 24

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

991

House No.

2873

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

L. H. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.