

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3983

DATE INSPECTED 8/8/38

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

176'

HOUSE NO. 211

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

176'

7' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John Thayer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

AUG 9 '38

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3983

PERMIT TO TAP SEWER

MASSILLON, OHIO,

8-8

19

RECEIVED OF

R. M. [Signature]

FEE OF \$ *2.00*

FOR WHICH PERMISSION IS GRANTED

[Signature]

TO TAP

[Signature]

SEWER, ON THE

South

OF

North T & E

AVE., TYPE OF STREET

ST.,

Brick

THE PREMISES BEING LOT No.

75

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

[Signature]

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.