

3
28

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o. 3984

DATE INSPECTED

8/10/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

273

HOUSE NO.

429

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

173'

3' deep

WAS LATERAL AT CURB?

Yes

WAS ATTACHED TO MAIN

Yes

NAME OF CONTRACTOR

Jac Cheroony

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

187th ST., N.W.

HOUSE.

3"

N →

8' deep
42'
3' deep
62'

M.H.O

273'

SIGNED

John E. Humer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

AUG 11 38

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3984

PERMIT TO TAP SEWER

MASSILLON, OHIO, 79 1919

RECEIVED OF Robert Long

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Robert Long

TO TAP Sanitary

SEWER. ON THE West

OF 18th St.

AVE., TYPE OF STREET dent
ST.,

THE PREMISES BEING LOT No. 5042

HOUSE No. 429

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bob Long

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.