

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3995

DATE INSPECTED 9/9/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

148

HOUSE NO. 783

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

148 - 6' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes


NAME OF CONTRACTOR

Geo Earley

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LAWTON AVE. S.E.



148

SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/9/38

REMARKS:

2' from corner to cellar drain 16' from corner of h
to house connection

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3995

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/9 1919

RECEIVED OF Geo. Early

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Adam Johnson

TO TAP Sanitary

SEWER ON THE West

OF Lancaster St. E.

AVE., TYPE OF STREET dirt
ST.,

THE PREMISES BEING LOT No. 5190

House No. 783

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Geo. Early

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.