

9
11

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4007

DATE INSPECTED 11/10/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

65'

HOUSE No. 2957

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

65' - 8" d

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes


NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

HOUSE LINCOLN WAX. N.W.



Found lateral sh
from measurements

SIGNED John E. Chamber
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/10/38

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4007

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/9 19

RECEIVED OF

M. H. Andrews

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

M. H. Andrews

TO TAP

sanitary

SEWER ON THE

South

OF

Lincoln Highway

AVE., TYPE OF STREET
ST.,

paved

THE PREMISES BEING LOT No.

10250

House No.

2957

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

L. W. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.