

N^o. 4011

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

AND SIGNED WHEN RETURNED

Gave Lateral 16" fall from main to
basement. $\frac{3}{12}$ DATE INSPECTED 11/30/38IF SO HOW AND LOCATION FROM
FIRST MANHOLE ~~DOWN~~ STREAM76' at main 3'6" deepHOUSE NO. 728

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 4" up~~DOWN~~ STREAM TO DITCH AT
CURB LINE AND DEPTH74' at curbWAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR


SmartWAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

VOGAL AVE, NE



This lateral relaid
could not get fall enough
for cellar drainage,
and was told by Mrs.
Baker present occupant to raise
enough in basement to keep sewage
from backing up.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

JAN 14 39

REMARKS:

Relaid lateral from main

3/12
1 oiloch

No 4011

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

11/26

19

RECEIVED OF

L. H. Smart

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Harold H. Smith

TO TAP

Sanitary

SEWER. ON THE

North

OF

Vogel Ave NE

AVE., TYPE OF STREET
St.,

dist

THE PREMISES BEING LOT No.

5240

House No.

728

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

L. H. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.